


No	Series	Designation	Photo	Applicable handrail diameter (D)	Surface treatment method	Note
1	Alu.all oy	Tee joint		φ32, φ35	Powder Coating	Containing 304 stainless steel bolts and nylon ball head nuts
2		Four-Way		φ32, φ35	Powder Coating	
3		Straight base		φ32, φ35	Powder Coating	
4		Heighten straight base		φ32, φ35	Powder Coating	
5		Base		φ32, φ35	Powder Coating	Including 304 stainless steel bolts, nylon ball head nuts, and bushings
6		Heighten base		φ32, φ35	Powder Coating	
7		Baffle clamp		φ32, φ35	Powder Coating	Including 304 stainless steel bolts, nylon ball head nuts, and rubber pad
8	Alu.all oy step series	Tee joint		φ32, φ35	Powder Coating	Including 304 stainless steel step bolts and nuts
9		Four-Way		φ32, φ35	Powder Coating	
10		Heighten straight base		φ32, φ35	Powder Coating	Including 304 stainless steel step bolts, nuts, and bushings
11		Heighten base		φ32, φ35	Powder Coating	
12		Cup holder		φ32, φ35	Powder Coating	
13		Side base		φ32	Powder Coating	Including bushings
14		Window base (H27)		φ32, φ35	Powder Coating	

15		Window base (H40)		φ32. φ35	Powder Coating	Including 304 stainless steel bolts, nuts, and bushings
16		Window base (H60)		φ32. φ35	Powder Coating	
17		Window base (H80)		φ32. φ35	Powder Coating	
18		Baffle clamp		φ32. φ35	Powder Coating	Including 304 stainless steel bolts, nuts, and rubber pad
19		Three holes baffle clamp		φ32. φ35	Powder Coating	
20	Alu. alloy non exposed nail series	Tee joint		φ32. φ35	Powder Coating	Including 304 stainless steel bolts (no nuts required)
21		Four-Way		φ32. φ35	Powder Coating	
22		Baffle clamp		φ32. φ35	Powder Coating	Including 304 stainless steel bolts (no nuts required), bushings
23	Steel	Footstock		φ32. φ35	Powder Coating	Including 304 stainless steel bolts , nuts ,bushings
24	Stainless Steel	Footstock		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts , nuts ,bushings
25		Tee joint		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts (no nuts required)
26		Four-Way		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	
27		Spherical tee joint		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	
28		Spherical four-Way		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	
29		Straight base		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel step bolts, nuts, and bushings
30		Side base		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	no nuts
31	Stainless Steel	Baffle clamp		φ32. φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts (no nuts)

32	Floor connection base		φ32, φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts (no nuts required)
33	Cup holder		φ32, φ35	Wire drawing, Mirror face, polishing or Powder Coating	No need for bolts and nuts
34	Facade Circle base		φ32, φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts (no nuts required)
35	Fixed side façade base		φ32, φ35	Wire drawing, Mirror face, polishing or Powder Coating	Including 304 stainless steel bolts (no nuts required)